



Vessel: **M.V. SPLIT**

Type: Bulk carrier

Boiler: **TPK Nova, flame tube**

Year of construction: **1994**

Fuel: **Heavy Fuel Oil, 380 cst**

Problems: Large deposits of soot have been formed inside the flame tubes requiring frequent stoppage of the boiler for cleaning, causing time loss and increased fuel consumption.

Date of installation: **April 2008**

BEFORE

The boiler had to be stopped for cleaning every 700-1000 hours of work, depending on the duration of the voyage.

Upon arrival at ports, engine crew were busy with boiler cleaning, so they had less time for other necessary maintenance work.


AFTER

After 700 hours of operation, with **AEROVIT** installed, the boiler was opened for internal tube control. All tubes were clean and passable as if they were new.

After installation of **AEROVIT** in April 2008 the boiler has been working more than 6000 hours and has not been stopped for manual cleaning.

Technical superintendent from M.V. Split, Mr. Zdravko Kesić says:

„Because there is no need anymore for boiler cleaning, our crew has more time for regular maintenance work and this implies significant cost savings. Also due to efficient boiler performance, fuel savings has been noticed.“



JADROPILOU LTD
INTERNATIONAL MARITIME TRANSPORT
SPLIT - CROATIA 2A
TECHNICAL & PERSONNEL DEPARTMENT

30.03.2009

Zdravko Kesić
SPLIT. IN CHARGE

AEROVIT A/S

Korden 15 • DK - 8751 Gedved
Tel. +45 86 92 44 22 • Fax +45 86 92 29 19
CVR/VAT 28 49 28 71 • sales@aerovit.dk • www.aerovit.dk

